

OpenWrt

Firmware assessment summary

A summary of saved analysis results shown in the Reverser Space firmware walkthrough. Product captures were recorded on 2026-10-11.

Firmware input

OpenWrt 25.12.5, x86-64
openwrt-25.12.5-x86-64-generic-ext4-combined-efi.img
Firmware version: 25.12.5-x86-64

Recorded results

Observation	Count
Observed components	254
Binary observations	171
Advisory matches (all review states)	664
Open component matches	664
Matches with a fix available	594
Accepted evidence requirements	3 of 10 (30%)

Review the supporting views

1. [Component inventory](#): package versions and supporting identity evidence.
2. [Advisory assessment](#): matched advisories, affected components, available fixes, and review state.
3. [Firmware summary](#): saved inventory, advisory results, and evidence review progress.

Coverage and open work

Both detected filesystems were inspected. One BIOS boot region was detected but not analyzed, and 229 files were skipped. Seven evidence requirements are not accepted. No saved baseline comparison targets this firmware. Advisory matches do not establish exploitability, and evidence acceptance is not release approval.

Use the results in a review

Inspect the identity evidence behind each component observation. Review advisory applicability with the affected version and recorded evidence. Save the resulting decisions and follow-up questions with the firmware version.

[Explore the complete firmware walkthrough](#)

Reverser Space | Supply chain security for firmware and binaries | duckie@reverser.space